Schooner *Inland Seas*

ABANDON SHIP CHECKLIST

	PROCEDURES:	LOCATION	CREW
1	Signals: Hail “Prepare to abandon ship” Horn: 1 short blast = launch raft Horn: 7 shorts + 1 long = leave vessel	Ship’s Horn	Captain
2	Radio Maday message on VHF Chan. 16	Pilot house, aft cabin	Captain
3	Activate EPIRB, Water light	Lazy board, PFD box port side aft	Captain
4	Muster passengers and assist with donning PFD’s	Midship	Educator, Cook
5	Crew dons work vests or exposure jackets/suits	Pilot house, hanging locker passageway	All
6	Upon signal, launch life raft (IBA), secure amidships at gate	Foredeck	Mate, Deckhand +2
7	Launch stern boat	Stern davit	Captain
8	Assist passengers into life raft (upon signal)	Midship gate, Aboard raft	Deckhand Mate
9	Count passengers boarding raft, compare with manifest. Account for all aboard	Midship gate	Educator
10	After all passengers are in raft, Mate, Educator and Cook board raft.	Raft	Mate, Cook, Educator
11	After all passengers are in raft, Capt. and Deckhand board stern boat. Use stern boat to pick up any PIW’s, tow raft away from vessel.	Stern boat	Captain, Deckhand
	TO BE BROUGHT ABOARD RAFT / STERN BOAT:		
1	Flare Kit	Steering Box	Captain
2	Emergency (Abandon Ship) Kit	Steering Box	Captain
3	HH VHF Radios (2)	Pilot House, Aft Cabin	Capt., Mate
4	Ship’s Cell Phone in Zip Lock Bag	Pilot House	Mate
5	Ship’s Log	Pilot House or on Deck	Captain
6	Manifest	Pilot House	Educator/Cook
7	Medical Kits	Main Cabin over passageway	Educator/Cook
8	Blankets	Main Cabin	Educator/Cook
9	High Energy Food (granola bars, chocolate)	Galley	Educator/Cook
10	Extra Exposure Suits, Jackets	Main Cabin	Deckhand
11	Extra Flashlights	Pilot House, Nav. Desk	Mate
12	Foul Weather Gear	Main Cabin	Deckhand