SCHOONER INLAND SEAS

STATION BILL

	MAN OVERBOARD		FIRE		DAMAGE CONTROL		ABANDON SHIP		MOORING	
SIGNALS	Hail "Man Overboard"		Hail "Fire" + location. Rapid ringing of ship's bell for 10 seconds or more.		Rapid ringing of ship's bell for 10 seconds or more.		Hail: "Prepare to abandon ship" 1 short blast=launch raft 7 short blasts + 1 long blast = abandon ship now		"Mooring Stations"	
POSITION	STATION	DUTY	STATION	DUTY	STATION	DUTY	STATION	DUTY	STATION	DUTY
CAPTAIN	Helm	In command -Radio -Quick stop -Lower boat -Fix position -MOB pole	Helm	In command Radio Comms.	Helm	In command Radio Comms.	Helm	In command -Abandon ship boxes Radio/EPIRB Launch stern boat Radio.	Helm	In command Stern line #4
MATE	Rescue boat	Recover victim. Get HH radio. GPS button	Site of fire	Direct firefighters	Damage site	Lead repairs	Life raft, then waist	Launch raft Supervise boarding	Midship	Call clearances (line #3 if boat in use)
DECK HAND	Rescue Boat	Assist lowering boat Recover victim	Site of fire	Bring fire equipment, Assist mate	Engine room, then Damage Site	Set bilge pump manifold. Bring DC equipment, Assist mate	Life raft, then waist	Assist mate Launch raft Secure painter	On deck	Spring line #3 Stern boat as needed
COOK/LEAD	Aft	Watch & point Aloft **After Victim Recovery:** Medical Kits, Oxygen, Defibrillator, blankets, Lower ladder	Pilot house, then on deck	Start fire pump Shut off inverter Close vents & LPG valve. Muster students Relay to firefighters	On Deck	Muster students Ready medical kit, Assist as needed	Life raft, then waist	Manifest Student count Distribute PFD's Bring first aid kits, blankets, work vests. Assist w/raft Assist boarding	On deck	Bow line #1 Directions to boat operator

NOTE: Dismissal from stations = 3 short blasts or rings on bell